

1 April February 2019

John Scandrett
Dairy Green Ltd.
10 Kinloch Street
PO Box 5003
Waikiwi
INVERCARGILL


RE: South Pro Drop Test, 20146428 February 2019

Dear John

At your request, we have reviewed the data collected for the above test. From this we confirm that:

1. The raw data collected via our Neon data collection system is as you have stated.
2. There were no significant complicating factors during the test, though because of conditions it was necessary to inspect the load cell data in detail to determine evaporation.
3. Your conclusion that leakage from the pond complies with the Council's effluent discharge rule appears to be correct.

Yours faithfully



Jeremy Bulleid
NIWA Instrument Systems