

A case study: linking catchment land use management to lake water quality

Keryn Roberts *Environmental scientist – estuaries and lakes*



Acknowledgements

- Nick Ward (Team Leader Ecosystem Response)
- Dianne Elliotte (Contractor Aquatech)
- Chris Owen (Contractor Southern Waterways)
- Rob Williamson (Science Assistant)
- James Dare (Previous Lake Scientist now at BoP RC)
- Simon Mapp (Compliance Manager)
- Nathan Cruickshank (Team Leader Land and Water Services)
- Landowners in the Lake Vincent Catchment

Coastal Lakes Programme

LAKE GEORGE



LAKE VINCENT



THE RESERVOIR



What's the problem?

- Catchments are intensively used for agriculture
- Declining water quality in coastal lakes
- Increased incidences of algal and cyanobacterial blooms


Case Study: Lake Vincent

James Dare, Simon Mapp, Nathan Cruickshank, Lake Vincent Land Owners

Between 2004 to 2016 water quality declined


Characterisation & investigation

Lake Vincent Catchment Management Proposal




Identifying problem areas


Wintering to lake edge




Self feed pads

Silage storage near inlet





Self feed pads



EMI mapping of effluent

Retired 'problem' self feed pad near inlet

Wintering



Fencing and exclusion of stock from lake margins




Riparian planting

Outcomes

Improved land use management

 Lower TN and TP for 2017 compared to 2016*



Integration

Water quality is linked to catchment land use therefore <u>holistic</u> management approaches are needed.

To support **on the ground changes** that improve the water quality of our coastal lakes we need to take a **cross divisional approach** within council to **support landowners**.